




TEST #1	DEPTH	DESCRIPTION	NOTES
1	0.0 - 0.6'	BROWN SILTY PDSOL	MOTTLING OBSERVED @ .45'
	0.6 - 0.9'	BROWN SILT	NO GROUNDWATERS OBSERVED
2	0.9 - 1.6'	BROWN SILT	NO GROUNDWATERS OBSERVED
	1.6 - 2.1'	BROWN SILT	NO GROUNDWATERS OBSERVED
3	2.1 - 2.7'	BROWN SILTY PDSOL	NO GROUNDWATERS OBSERVED
	2.7 - 3.0'	GRAVELLY BROWN CLAY	
	3.0 - 3.7'	BROWN SILT	MOTTLING OBSERVED @ .30'
	3.7 - 4.0'	GRAVELLY BROWN CLAY	NO GROUNDWATERS OBSERVED
4	4.0 - 4.6'	BROWN SILT	NO GROUNDWATERS OBSERVED
	4.6 - 5.2'	BROWN SILT	NO GROUNDWATERS OBSERVED
	5.2 - 7.2'	GRAVELLY BROWN CLAY	
5	0.0 - 0.8'	BROWN SILTY PDSOL	MOTTLING OBSERVED @ .44'
	0.8 - 4.4'	BROWN SILT	NO GROUNDWATERS OBSERVED
	4.4 - 7.2'	GRAVELLY BROWN CLAY	
6	0.0 - 0.8'	BROWN SILTY PDSOL	MOTTLING OBSERVED @ .54'
	0.8 - 8.4'	BROWN SILT	NO GROUNDWATERS OBSERVED
	8.4 - 54.7'	GRAVELLY BROWN CLAY	

PROPERTY LINE	
EXISTING GAS VALVE	
EXISTING WATER VALVE	
EXISTING HYDRANT	
EXISTING UTILITY POLE	
EXISTING SIGN	
EXISTING CATCH BASIN	
EXISTING SANITARY MANHOLE	
EXISTING SANITARY SEWER	
EXISTING WATERMAIN	
EXISTING OVERHEAD WIRE	
EXISTING CONTOUR	
WETLAND BOUNDARY	
PROPOSED IMPACT	
PROPOSED TEMPORARY IMPACT	
EXISTING FILLING	
PROPOSED CLEARING LIMITS	
PROPOSED STORM SEWER	
PROPOSED CATCH BASIN	
PROPOSED LIGHT POLE	
PROPOSED WALL LIGHT	
TEST PIT	

LEGEND

Red Price Chopper

60' WIDE LG. HIGH PRESSURE GAS
EASTERN BOOK 1988 PAGE 77