Mike Cirillo Staked out corners of lot. Owner will use these as references for fence location.

Good SIDE OUT
CD
8/19/08

LISA DAVIS
136 MOSHER RD
DELMAR, 12054