

BETHLEHEM SEWER DISTRICT



Town of Bethlehem
445 Delaware Avenue
Delmar, New York 12054

Building Sewer Inspection Report

Permit No: _____

Name of Owner Kara KowalskiAddress 14 Gardener TerrLocation of Connection or Tap 1+97 Feet _____ N S E W from M.H. # 182APipe Size 6" Material: Clay Iron A-C ABS SDR 26Sewer Depth at Property Line 5 ft Sewer Slope YesJoints Tight Yes Alignment Straight YesSolid Bedding (Tamped) under pipe YesExtra Cleanout if sewer over 100 feet long N/A

Outside Pit (Trap) (Grease) _____

Septic Tank and/or Seepage Pit(s): Pumped _____ Filled (type) _____ Removed _____

Grinder Pump: Inside _____ Outside _____

Cleanouts _____ Trap _____ Fresh Air Inlet _____

Fixtures Connected:

Number	Kind	Number	Kind
	Kitchen Sinks		Bath tubs
	Lavatories		Showers
	Laundry		Garbage Grinders
	Urinals		
	Water Closets		

Illegal Connections

Foundation Drain _____ Down Spouts _____

Sump Pump _____ Cellar Drain _____

Remarks: SEE DRAWING ON BACKThe name & address of the person or firm making this installation is: Trinity ConstructionName of Inspector Donald Kowalski Date of Inspection 9/2/14

Connection Approved _____

Town of Bethlehem

ALBANY COUNTY • NEW YORK

Department of Public Works

445 DELAWARE AVENUE

DELMAR, NEW YORK 12054

SHEET _____ OF _____
BY _____ DATE _____
SUBJECT _____

