

BETHLEHEM SEWER DISTRICT



Town of Bethlehem
445 Delaware Avenue
Delmar, New York 12054

Building Sewer Inspection Report

Permit No: _____

Name of Owner Michael Andriano

Address 18 Gardener Terr

Location of Connection or Tap 2+40 Feet N S E W from M.H. # 182A

Pipe Size 6" Material: Clay Iron A-C ABS SDR 26

Sewer Depth at Property Line 5 ft Sewer Slope YES

Joints Tight YES Alignment Straight YES

Solid Bedding (Tamped) under pipe YES

Extra Cleanout if sewer over 100 feet long N/A

Outside Pit (Trap) (Grease) _____

Septic Tank and/or Seepage Pit(s): Pumped _____ Filled (type) _____ Removed _____

Grinder Pump: Inside _____ Outside _____

Cleanouts _____ Trap _____ Fresh Air Inlet _____

Fixtures Connected:

<u>Number</u>	<u>Kind</u>	<u>Number</u>	<u>Kind</u>
_____	Kitchen Sinks	_____	Bath tubs
_____	Lavatories	_____	Showers
_____	Laundry	_____	Garbage Grinders
_____	Urinals	_____	
_____	Water Closets	_____	

Illegal Connections _____

Foundation Drain _____ Down Spouts _____

Sump Pump _____ Cellar Drain _____

Remarks: SEE DRAWING ON BACK

The name & address of the person or firm making this installation is: Trinity Construction

Name of Inspector Donald Kavork Date of Inspection 9/2/14

Connection Approved _____

Town of Bethlehem

ALBANY COUNTY • NEW YORK

Department of Public Works

445 DELAWARE AVENUE

DELMAR, NEW YORK 12054

SHEET _____ OF _____
BY _____ DATE _____
SUBJECT _____

