

BETHLEHEM SEWER DISTRICT



Town of Bethlehem
445 Delaware Avenue
Delmar, New York 12054

Building Sewer Inspection Report

Permit No: _____

Name of Owner Kenneth Evans

Address 488 Kenwood Ave

Location of Connection or Tap 1+63.5 Feet _____ N S E W from M.H. # 179A

Pipe Size 6" Material: Clay Iron A-C ABS SDR26

Sewer Depth at Property Line 4ft Sewer Slope YES

Joints Tight YES Alignment Straight YES

Solid Bedding (Tamped) under pipe YES

Extra Cleanout if sewer over 100 feet long N/A

Outside Pit (Trap) (Grease) _____

Septic Tank and/or Seepage Pit(s): Pumped _____ Filled (type) _____ Removed _____

Grinder Pump: Inside _____ Outside _____

Cleanouts _____ Trap _____ Fresh Air Inlet _____

Fixtures Connected:

Number	Kind	Number	Kind
_____	Kitchen Sinks	_____	Bath tubs
_____	Lavatories	_____	Showers
_____	Laundry	_____	Garbage Grinders
_____	Urinals	_____	_____
_____	Water Closets	_____	_____

Illegal Connections _____

Foundation Drain _____ Down Spouts _____

Sump Pump _____ Cellar Drain _____

Remarks: SEE DRAWING ON BACK

The name & address of the person of firm making this installation is: Trinity Construction

Name of Inspector Donald Kauraat Date of Inspection 8/15/14

Connection Approved _____ Date _____

445 DELAWARE AVENUE
DELMAR, NEW YORK 12054

SUBJECT _____

